




HAND-CAST SCULPTURES

lead-free

www.CreativeCastings.com



Hummingbird 8306-04

Construction Tips:

Before you start, remember to deburr and clean your pieces if necessary.

You may pre-polish your piece with a dry #0000 steel wool pad.

Assemble your pieces with a cool iron. This metal has a melting point of 450° F. A hot iron could result in melting of the product.

After your glass is attached, piece should be thoroughly cleaned with hot soapy water, flux remover or degreaser.

Remember to apply any patinas, if desired, immediately after cleaning. Use a toothbrush to get into tight areas.

Always wear eye protection.

After your piece is completed, details and highlights can be brought out by lightly buffing with a clean, dry #0000 steel wool pad.

